

Case 1 5 : Worker fell from framework, hit brace, and fell down to ground

Because floorboards were not sufficiently tied down, worker fell and was injured when climbing up and down to assemble scaffolding.

Cause

- Handrail leading scaffolding was not used.
- Fall prevention device was not used.
- Floorboards were inadequately installed, and work was performed under unsafe conditions.

Result

- Bruises on back and back of head

Action

- When worker climbed onto scaffold to assemble, he fell down and injured because floorboards were insufficiently tied down.

Lesson

- ① Assemble scaffolding by handrail leading method.
- ② Use fall prevention devices when assembling and dismantling scaffolding.

