

## Case 4 : Worker lost his balance and fell down while dismantling scaffolding

While dismantling scaffolding boards, the worker was working with using the fall prevention device on a single pipe, and he temporarily removed the fall prevention device to move on to the next job. When moving, the clamps on the single pipe which were supporting the scaffolding boards were come off, and the worker lost his balance and fell down.

### Cause

- The fall prevention device was removed while working in a high place.

### Result

- Injuries (heel fracture, elbow fracture, sprained ankle)

### Lesson

- Use fall prevention devices when assembling and dismantling scaffolding.

### Action

- When worker temporarily removed the fall prevention device, scaffolding boards were come off, and he lost his balance and fell down.

