

Case 8 : Operator got caught in and injured when footboard slipped and backhoe tipped over

When backhoe was loaded onto truck using footboards, a footboard shifted and backhoe tipped over, and operator's foot got caught in under backhoe, resulting in an injury.

