

# Case 1 O : Worker suspended in midair when falsework on slope collapsed

While placing concrete for the upper part of the slope, a falsework slipped and the upper formwork collapsed, a worker was suspended in midair on the formwork.

