

Case 1 1 : When worker tried to load tools onto vehicle in an unreasonable posture, he fell down into opening of road deck

When worker reached out with hands in unreasonable posture and tried to load tools onto seat of Unicrane, he lost his balance and fell down into opening in road deck panel, hit his foot on water pipe and injured.

