Case 1 4: Worker fell down from cargo bed of dump truck and injured

When a worker tried to climb onto the back of a dump truck to pass the materials, he slipped and fell down, resulting in an injury.

Cause

- Worker tried to climb onto back of truck with gate raised.
- Besides being slippery from rain, worker was advanced in age.
- Dump truck cargo bed was not cleaned up.

Action

• When worker tried to climb onto dump truck bed, they slipped and fell down.

Result

Left wrist and left femur fracture

Lesson

- When check the working procedures, workers should be assigned in accordance with their abilities.
- ③Dump truck cargo beds should be cleaned up at all times.

When worker tried to climb onto dump truck bed to pass the material. He slipped and he fell down.

He fell to the ground with their left side facing.

After falling, he lied down with his left side facing up.