

Case 5 : Traffic guide got caught in between tire roller and utility pole

Traffic guide helping with paving work was injured when got caught in between a backing up tire roller and utility pole.

